Map ID MAP FINDINGS

Direction Distance

Distance EDR ID Number
Elevation Site EDR ID Number

1511 JAMES BEATRICE NY Spills S104647730 ENE 4648 BEDFORD AVE N/A

> 1 1.892 mi. 9990 ft.

Relative: SPILLS:

BROOKLYN, NY

HigherName:JAMES BEATRICEActual:Address:4648 BEDFORD AVE10 ft.City,State,Zip:BROOKLYN, NY

 Spill Number/Closed Date:
 9806366 / 2006-05-16

 Facility ID:
 9806366

 Facility Type:
 ER

 Facility Type:
 ER

 DER Facility ID:
 237507

 Site ID:
 293431

 DEC Region:
 2

Spill Cause: Equipment Failure

 Spill Class:
 C3

 SWIS:
 2401

 Spill Date:
 1998-08-22

 Investigator:
 NEPUTNAM

 Referred To:
 Not reported

 Reported to Dept:
 1998-08-22

 CID:
 207

Water Affected:
Spill Source:
Spill Notifier:
Cleanup Ceased:
Cleanup Meets Std:

Not reported
Private Dwelling
Local Agency
Not reported
True

Last Inspection: Not reported Recommended Penalty: False UST Trust: False Remediation Phase: 0

Date Entered In Computer: 1998-08-22
Spill Record Last Update: 2006-05-16
Spiller Name: Not reported
Spiller Company: JAMES BEATRICE
Spiller Address: 4648 BEDFORD AVE

Spiller Company: 001

Contact Name: JAMES BEATRICE

DEC Memo: "5/16/06- Mike - Contacted owner, no longer has records of tank test.

Contacted Petro Oil, no spill occured during tank failure, had tank repaired and tested again on 3/2/1999 which it passed. Also passed another test is 2001. 3/16/06 - Nathan - 718-934-5431 owner needs to

be contacted. Prior to Sept, 2004 data translation this spill

Lead DEC Field was M TIBBE "

Remarks: "TANK VALVE ON TANK FAILED - SERVICE MAN ON SCENE"

293431

.00

All Materials: Site ID:

Recovered:

Operable Unit ID: 1067546 Operable Unit: 01 317528 Material ID: Material Code: 0001A Material Name: #2 fuel oil Case No.: Not reported Material FA: Petroleum Quantity: .00 Units: G

Map ID Direction		MAP FINDINGS		
Distance Elevation	Site		Database(s)	EDR ID Number EPA ID Number

Oxygenate: Not reported